PATENT

Certificate
AUG 2 0 2004
of Correction

In re Patent of:

Per-Åke Johansson et al.

Patent No.:

6,757,065 BI

Issue Date:

June 29, 2004 09/890,056

Serial No.:

January 8, 2002

Filed: Title:

METHOD OF DETERMINING AN ILLUMINATED SURFACE

Atty Docket No.:

STOCK-02

Cincinnati, OH

August 16, 2004

Commissioner for Patents

Attn: Certificate of Correction Branch

P.O. Box 1450

Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKES (37 C.F.R. § 1.322(a))

Sir:

It is respectfully requested that a Certificate of Correction be issued for the patent identified in the heading. The patent contains printing errors that occurred through the fault of the Patent Office as follows:

Column 1

Line 21, change "lest" to -test--.

Column 2

Line 49, change "where α is the angle" to read --where α is the angle--.

Column 3

Line 26, change "(in the form of 2 mu)" to read --(in the form of 2 π iu)--.

Column 4

Line 15, change "where y=the angle" to read --where γ = the angle--.

Line 41, change "according to, FIGS. 9A and 9B" to read --according to FIGS. 9A and 9B--.

Column 5, Claim 1

Line 30, change "tanY" to read --tan γ--.

Line 33, change "where Y is the angle" to read --where γ is the angle--.

In accordance with the established procedure for handling such certificates, two copies of PTO-1050 are enclosed herewith listing the errors.

Applicants do not believe that any other fees are due in connection with this response. However, if such petition is due or any other fees are necessary, the Commissioner may consider this to be a request for such and charge any necessary fees to deposit account 23-3000.

Respectfully submitted, WOOD, HERRON & EVANS, L.L.P.

By: William R. Allen, Reg. No. 48,389

2700 Carew Tower Cincinnati, OH 45202 (513) 241-2324

Printer's Trim Line

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,757,065 **B**\

DATED

: June 29, 2004

INVENTOR(S): Per-Åke Johansson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1

Line 21, change "lest" to --test--.

Column 2

Line 49, change "where α is the angle" to read --where α is the angle--.

Column 3

Line 26, change "(in the form of 2 mu)" to read --(in the form of 2 π iu)--

Column_4

Line 15, change "where y=the angle" to read --where γ = the angle--.

Line 41, change "according to, FIGS. 9A and 9B" to read --according to FIGS. 9A and 9B--.

Column 5, Claim 1

Line 30, change "tanY" to read --tan γ--.

Line 33, change "where Y is the angle" to read --where γ is the angle--.

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917

PATENT NO. <u>6,757,065</u> B) No. of add'l copies @ 50¢ per page:

Printer's Trim Line

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,757,065 6

DATED : June 29, 2004

INVENTOR(S) : Per-Åke Johansson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1

Line 21, change "lest" to --test--.

Column 2

Line 49, change "where α is the angle" to read --where α is the angle--.

Column 3

Line 26, change "(in the form of 2 mu)" to read --(in the form of 2 π iu)--

Column 4

Line 15, change "where y=the angle" to read --where γ = the angle--.

Line 41, change "according to, FIGS. 9A and 9B" to read --according to FIGS. 9A and 9B--.

Column 5, Claim 1

Line 30, change "tanY" to read --tan γ--.

Line 33, change "where Y is the angle" to read --where γ is the angle--.

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917 PATENT NO. <u>6,757,065</u> (b) No. of add'l copies @ 50¢ per page: __

'AUG 23 2000